


## Brake Hydraulic Line Kits

OVER 100 SKUS AVAILABLE



**919-235**  
Ford Taurus 2006-00,  
Mercury Sable 2005-00  
Pop Code: C | VIO: 1,255,503

- All lines and fittings included for a complete installation

**FAILURE MODE:**

- Original steel lines rust from exposure to moisture and corrosive road treatments, which result in fuel leaks and loss of brake power



**OE PROBLEM:**

Original steel lines rust from exposure to moisture and corrosive road treatments.



Upgraded stainless steel resists rust and corrosion. The pre-formed sectional design saves installation time.

## 4WD Actuator Valve



Stops oil flow to the differential clutch pack to prevent catastrophic failure of the rear differential

- Built with corrosion resistant metal and robust plastic for a longer service life
- Easy-to-install, just plug into mating wiring harness
- Quality-fit tested to ensure trouble-free installation

**600-121**

Buick 2007-02, Chevrolet 2006-02, Oldsmobile 2004-02,  
Pontiac 2006-01, Saturn 2006-05

Pop Code: C | VIO: 773,368

**FAILURE MODE:**

- Failure results in an inoperable AWD system and illumination of the service AWD light

## Transmission Control Modules

OVER 15 SKUS AVAILABLE



**ONLY AVAILABLE IN AFTERMARKET FROM DORMAN**

- Sends signal to command transmission to shift in and out of gears
- Completely remanufactured and vehicle simulator tested for durability and quality assurance
- Built with higher grade electronic components

**FAILURE MODE:**

- Failure of the original TCM is caused by excess heat and vibration; the resulting loss of communication forces the transmission into limp mode or prevents the transmission from engaging a gear

**609-200**

Chevrolet, GMC 2008-06

Pop Code: C | VIO: 456,867

## Engine Coolant Thermostat Housing Flange Repair Kit



**OE PROBLEM:** The original housing corrodes and warps over time and eventually leaks, resulting in an expensive replacement.



**OE FIX:** Add-on replacement part provides an extra clamping force to re-seal and secure the thermostat housing, instead of replacing the entire assembly.

**FAILURE MODE:**

- Coolant leaks at the thermostat housing and vehicle engine overheating

**904-486**

Ford 2003-94

Pop Code: D | VIO: 1,440,145

## Shift Interlock Solenoids

OVER 15 SKUS AVAILABLE



**ONLY AVAILABLE IN AFTERMARKET FROM DORMAN**

- Essential safety mechanism - prevents vehicle from shifting out of park until the driver's foot is on the brake pedal
- Direct replacement for a proper fit every time

**FAILURE MODE:**

- Original shifter fails to actuate internal circuit, resulting in the inability to shift vehicle out of park

**924-971**

Ford 2017-09, Ford 1998-94

Pop Code: C | VIO: 791,989

Think It's Dealer Only? **Check Dorman First!** | [www.DormanProducts.com](http://www.DormanProducts.com)



## Brake Caliper Bracket Bolts

OVER 20 SKUS AVAILABLE



Bolts used to fasten the brake caliper bracket to the steering knuckle

- Pre-coated with thread lock to prevent bolt from loosening
- Easy-to-install, direct-fit replacement

**FAILURE MODE:**

- The original bolt breaks or strips during brake service

**14962**

Chrysler 2018-07, Mercedes-Benz 2017-06,  
Volkswagen 2014-09

Pop Code: D | VIO: 6,557,149

## Power Steering Fluid Reservoirs

OVER 75 SKUS AVAILABLE



Provides power steering fluid to the pump

- Built with premium plastic material to withstand fluctuating underhood temperatures
- All power steering fluid reservoirs include caps

**FAILURE MODE:**

- Internal filter screen clogs, damage during power steering pump repair, cracking, damaged or missing cap, and collision

**603-712**

Honda Accord 2002-98

Pop Code: B | VIO: 872,900

## Heater Hose Assemblies

OVER 100 SKUS AVAILABLE



**ONLY AVAILABLE IN AFTERMARKET FROM DORMAN**

- Helps maintain engine coolant circulation
- Quality-engineered to resist corrosion and coolant leaks for a longer service life
- Direct replacement for original equipment designs

**FAILURE MODE:**

- The original metal tube corrodes, cracks and leaks over time, resulting in loss of pressure

**626-554**

Toyota 4Runner 2010, Hiace 2016-12, Hilux 2017-12

Pop Code: C | VIO: 225,868

## Dash Board Air Vents

OVER 30 SKUS AVAILABLE



Directs air into vehicle cabin

- Replacement ensures continuous control over air flow direction
- Multiple vent options (left, right and center) available on specific applications
- Direct replacement for original equipment designs

**FAILURE MODE:**

- Normal wear and tear from continuous use, results in damaged or loose vent

**74932**

Ford F-150, Lobo 2014-09

Pop Code: C | VIO: 2,570,564

## Power Seat Control Module



Controls power seat functions

- All new circuit board components ensures a longer service life
- Completely remanufactured and vehicle simulator tested for durability and quality assurance

**FAILURE MODE:**

- The original module loses connectivity and results in the inability to adjust seat

**902-011**

Buick 2011-08, Cadillac, Chevrolet, GMC 2013-07,  
Hummer 2009-08, Saturn 2010-07

Pop Code: SO | VIO: 6,123,752

## Tailgate Light



Indicator light for wide vehicles

- Provides up to 10 times more brightness, quick illumination and high efficiency for a longer service life
- Wiring harness included - no wire splicing necessary
- Easy-to-install, direct-fit replacement

**FAILURE MODE:**

- Collision damage, bulb failure, results in no light being emitted

**923-024**

Ford 2011-99

Pop Code: D | VIO: 3,604,031

Think It's Dealer Only? **Check Dorman First!** | [www.DormanProducts.com](http://www.DormanProducts.com)