

Exhaust Manifold to Cylinder Head Repair Clamp



- Prevents exhaust leaks
- Clamp and bolts included for a complete repair

FAILURE MODE:

- The original manifold bolts rust and break off causing exhaust leaks at the cylinder head

917-108

Chevrolet, GMC 2009-99;
Hummer 2007-03

Pop Code: B | VIO: 8,713,982



BROKEN BOLT HEAD


OE PROBLEM:

Manifold studs commonly break, requiring a labor-intensive job of extracting broken studs.



Dorman's Manifold Clamp eliminates the need to extract broken studs by providing an external clamping solution.

Truck Bed Floor Support



OE PROBLEM: Original bed supports corrode easily, and the Dealer does not offer as a separate replacement option.



OE FIX: The Dorman repair saves you money by replacing the rusted original supports, not the entire truck bed assembly.

- Includes bed hardware for a complete repair
- Direct-fit replacement for popular Ford truck applications

926-988

Ford F-250/350 Super Duty 2017-99

Pop Code: C | VIO: 4,072,172

Key Fob



OE PROBLEM: When the original key fob fails the Dealer requires an expensive replacement and programming.



OE FIX: Available as a complete unit, including a user-friendly programming tool to easily sync the remote to the vehicle in less than five minutes.

99360

Chrysler 2016-12, Dodge 2017-12, Ram 2012-11

Pop Code: B | VIO: 1,855,888

Suspension Stabilizer Bars

OVER 45 SKUS AVAILABLE



Minimizes lateral body roll and ride control

- Re-engineered with a solid forged design to eliminate ends from breaking off due to corrosion
- Includes all bushings, brackets and mounting hardware for a complete repair

FAILURE MODE:

- Corrosion, extreme suspension articulation and general wear and tear results in excessive body roll

927-113

Chevrolet Equinox 2009-05, Pontiac Torrent 2009-06,
Saturn Vue 2007-02

Pop Code: C | VIO: 682,411

Windshield Washer Reservoirs

OVER 100 SKUS AVAILABLE



Provides windshield wiper fluid to the windshield

- Built with premium plastic material to withstand fluctuating underhood temperatures
- Fluid level sensor washer pump are included
- All windshield washer reservoirs include caps

FAILURE MODE:

- Collision damage, cracking and use of fluids other than wiper fluid results in fluid leaks

603-662

Dodge 2013-09, Ram 2018-10

Pop Code: B | VIO: 1,783,376

Think It's Dealer Only? **Check Dorman First!** | www.DormanProducts.com



Steering Rack and Pinion Mount Bushing



OE PROBLEM: When the original steering rack bushing fails the Dealer requires an expensive replacement of the entire steering rack.



OE FIX: Replace the failed original bushing, instead of the entire steering rack, saving you time, money and labor.

- Two-piece design for ease of installation

FAILURE MODE:

- Rubber bushings deteriorate over time and results in loose steering or clunking noises

523-267

Chevrolet, GMC 2014-07

Pop Code: B | VIO: 3,668,334

Liftgate Release Switch Seal

NEW



OE PROBLEM: The original seal deteriorates over time, resulting in an expensive replacement of the liftgate switch.



OE FIX: Easily replace the failed original seal, instead of the entire liftgate switch, saving time, money and labor.

FAILURE MODE:

- The original switch cover deteriorates over time, exposing internal switches to debris and weather

926-098

Lexus 2012-04, Scion 2010-05, Toyota 2017-03

Pop Code: B | VIO: 4,418,101

Turbocharger Up Pipe Hardware Kit



DIESEL

679-005-H

Ford 2003-99, IC Corporation 2004-02, International 2004-96

Pop Code: C | VIO: 1,187,132

Seals the up pipes from the exhaust manifold to the turbo system

- All required gaskets and hardware included for a complete repair
- Prevents exhaust leaks and loss of fuel mileage

FAILURE MODE:

- Failure results in loss of power, poor fuel mileage and exhaust leaks

Engine Coolant Pipe O-Ring Kit



OE PROBLEM: When the original O-ring degrades, the Dealer requires the purchase of a new coolant tee with O-ring pre-installed.



OE FIX: Available separately, replace the damaged O-ring, instead of purchasing a new coolant tee.

FAILURE MODE:

- The original O-ring deteriorates over time and eventually causes coolant leaks

926-168

Ford 2018-11, Lincoln 2017-15

Pop Code: A | VIO: 4,101,927

HVAC Control Modules

OVER 75 SKUS AVAILABLE



599-012

Chevrolet, GMC 2001-90

Pop Code: C | VIO: 1,394,388

Controls various cabin temperature settings

- Ready-to-install - plug-and-play design requires no OE programming
- 100% replacement of LED backlight bulbs

FAILURE MODE:

- Lights go dark, fan and temperature control failure, inability to change modes, temperature and fan speeds

Wheel Hub Dust Shield



Protects the front hub seal from dirt and debris

- Rust-resistant steel construction protects wheel from dirt, debris and moisture
- All hardware included for a complete installation

FAILURE MODE:

- Over time rust, snow, and ice causes the original front hub seal to leak/weep

600-233

Ford 2017-05

Pop Code: D | VIO: 2,356,392