

Radiator Fan Assembly




621-526XD
Dodge Charger 2018-12
Pop Code: A | VIO: 473,968

- 10x service life vs. OE and competitor parts
- Ideal for heavy use applications such as law enforcement, fleet, performance vehicles
- Complete assembly including shroud, motor and blade

FAILURE MODE:

- Failure signs include illumination of the hot temperature light, engine overheating and fan not operating



OE PROBLEM:

Under-engineered motor. Fails prematurely due to high use cooling powerful engine.



OE FIX

Upgraded motor with a proven, brushless motor design (BLDC), 10x the service life vs. the original design!

Ignition Lock Cylinder



924-784
Chrysler 2007-98, Dodge 2009-98,
Jeep 2005-98, Plymouth 2001-97
Pop Code: B | VIO: 7,046,490

OE PROBLEM: When the original ignition key fails, the dealer requires an expensive replacement, plus programming.

OE FIX

OE FIX: Calibrates to the original ignition key, eliminating the need to disassemble the cylinder for recoding before use.

- Easily codes with the turn of the key - no assembly required

FAILURE MODE:

- Tumbler wears out over time, resulting in binding and the inability to turn key

HVAC Heater Hose Assembly



626-541
Ford F-150, Lobo 2017-11, Mustang 2018-11,
Lincoln Mark LT 2014-11
Pop Code: B | VIO: 1,503,769

OE PROBLEM: Original heater hose assemblies typically fail due to cracked plastic Y-connectors.

OE FIX

OE FIX: Y-connector material upgraded from plastic to aluminum for increased durability and a longer service life.

- Clamps included to assist with installation

FAILURE MODE:

- Original plastic Y-connector cracks over time and results in coolant leaks and loss of pressure

Engine Mount Bracket



917-189
Lexus 2008-96, Toyota 2009-94
Pop Code: B | VIO: 3,349,925

Supports engine position in the frame

- Includes required hardware for a complete installation
- Bracket is galvanized for added corrosion resistance
- Easy-to-install, direct-fit replacement

FAILURE MODE:

- The engine bracket has to be removed when servicing the timing belt and the hardware seizes to the mount

Radiator Shutter Assemblies

OVER 5 SKUS AVAILABLE



601-322
Ford Explorer, Police Interceptor Utility 2016-13
Pop Code: D | VIO: 915,828

ONLY AVAILABLE IN AFTERMARKET FROM DORMAN

- Regulates airflow through radiator to engine compartment
- Comes ready to install with motor for a complete repair
- No programming required

FAILURE MODE:

- Broken grille shutters or motor failure results in illumination of the check engine light and higher than normal engine temperatures

Think It's Dealer Only? **Check Dorman First!** | www.DormanProducts.com



Fuel Injection O-Ring Kits

OVER 15 SKUS AVAILABLE



Provides an air-tight seal around the fuel injectors

- O-rings are designed to combat brittleness, cracking and heat aging
- Recommended for replacement when servicing the fuel injectors

FAILURE MODE:
• Broken or leaking O-rings cause excess fuel consumption and results in smoke coming from tail pipe

904-312

Dodge Ram 2500/3500 5.9L Diesel 1998-94

Pop Code: D | VIO: 201,152

Fuel Lines - Stainless Steel Fuel Line Kit

OVER 10 SKUS AVAILABLE



OE PROBLEM: Original fuel lines rust from exposure to moisture and corrosive road treatments.



OE FIX: Upgraded to stainless steel to resist rust and corrosion. Pre-formed section design solution saves installation time.

- All lines and fittings included for a complete installation

FAILURE MODE:
• Rusts from exposure to moisture and corrosive road treatments, which results in fuel leaks and loss of pressure

919-845

Chevrolet Silverado, GMC Sierra 2010-04

Pop Code: B | VIO: 631,714

Brake Hydraulic Line Kits

OVER 100 SKUS AVAILABLE



OE PROBLEM: Original steel lines rust from exposure to moisture and corrosive road treatments.



OE FIX: Upgraded stainless steel resists rust and corrosion. Pre-formed section design solution saves installation time.

- All lines and fittings included for a complete installation

FAILURE MODE:
• Original steel lines rust from exposure to moisture and corrosive road treatments, which result in fuel leaks and loss of brake power

919-244

Ford F-250/F-350 Super Duty 2004-01

Pop Code: D | VIO: 609,283

Transmission Pan

OE PROBLEM: When the original filter and gasket fails, the dealer requires replacement of the entire transmission pan.



OE FIX: Available as a complete kit with a removable filter that can be serviced separately, without replacing the entire transmission pan.

- Includes required installation hardware for complete repair

FAILURE MODE:
• Impact and collision damage results in oil leaks

265-851

BMW 2013-04

Pop Code: D | VIO: 1,135,895

Automatic Transmission Filter Kit

OE PROBLEM: The filter and gasket is not available separately from the dealer, resulting in an expensive replacement.



OE FIX: Available separately, allowing replacement of the filter and gasket, without replacing the entire transmission pan.

- *Only compatible with Dorman transmission pans

FAILURE MODE:
• Poor running conditions, loss of power and decrease in transmission shift quality

265-851F

BMW 2013-04

Pop Code: W | VIO: 1,074,896

Integrated Control Modules

OVER 25 SKUS AVAILABLE



ALSO KNOWN AS: TOTALLY INTEGRATED POWER MODULE (TIPM)

- Controls a variety of electrical components throughout the vehicle, including windshield wipers, headlamps, radio and so much more
- Fully remanufactured and vehicle simulator-tested for quality assurance
- Updated with the most recent programming available
- Easy-to-install, plug-and-play repair solution; no special tools or programming required

FAILURE MODE:
• Internal circuit failure causes erratic electrical problems in original unit

599-949

Ram 1500/2500 2011

Pop Code: C | VIO: 166,073

Think It's Dealer Only? **Check Dorman First!** | www.DormanProducts.com